Notice



CORRECTION PRODUCTION CH	IANGE
SERVICE FLASH ADD INFORMATION	ON FILE NO.
Please add this notice to the Service Manual listed below. REVISION 0	
Category: COLOR TELEVISION	Date: JULY / 25 / 2011
Model:	Effective from : Chassis No. P50740-02
Destination: <u>U.S.A. / CANADA</u> REF : <u>No. SM780175-02</u>	
Manual. If the Service Manual Chass	sis No. does not match the unit's, additional Service is is similar to Chassis No. P50740-00. Only the

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

difference Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P50740-00 used in

1. IN THE SERVICE ADJUSTMENTS

Model DP50740 (SM780163).

The are no changes.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The are no changes.

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

July 2011 SMC

© Sanyo Manufacturing Corporation 2011